SUBJECT Port Informati	on, Basilan City, Isabela		
A PLACE ACQUIRED (BY SOURCE)	The state of the s		
A. A. Santana and Santana		ORR NO.	
DATE ACQUIRED (BY SOURCE)		OCI NO.	
		DATE DISTR. 5 7	n 54
DATE (OF INFO.)		NO. OF PAGES 2	
THIS BOCUMENT C	TAINS INFORMATION AFFECTING THE NATIONAL DEFENSE ATES, BITHIN THE MEARING OF TITLE 16. SECTIONS 700		
AND 794, OF THE	J.S. COJE, AS AMENDED. ITS TRANSMISSION OR REVE- TIENTS TO OR RECEIPT BY AN UNAUTHORIZED PERSON IS	NO. OF ENCLS.	

The office of Naval Intelligence (12ND, No 137-53) furnished the following information to CTA for TAC dissemination in accordance with par 3c of NSCID#7.

- 1. Approach Entrance. Approach to Isabela (6° 42.4'N 121° 58.1'E) should be made from the westward through the Malamaui Road and only during the daytime because of the shoals and banks in the vicinity which cannot be distinguished at night. From Malamaui Road either the Northern or Southern channel can be used to reach Isabela. The southern course is preferable because of the straight line approach while the northern course requires a turn in somewhat restricted waters. Both courses are exceptionally tell warked for daytime entry. Night time entry should be made only in emergencies at which time the Pilot has facilities to place temporary lights on the buoys marking the southern approach.
- 2. Southern Approach. On a southerst course leaving Molemani Island to Port, pick up Black Buoy No 1. At this point Red Buoys No 2 and No 4 will be plainly visible off the port boy. Ship can year eastward until mid-channel position is reached and course 8. true leads through channel.
- 3. Northern Approach. From Malamaui Road take the northwest channel between Moro Island and Malamaui with Red Buoys No 2 and No 4 marking the coral reefs to starboard. The white triangular range beacon guides to center channel course 69° 30' true. When abeam of Red Buoy No 4, Red Buoy No 6 can be seen to starboard. Change course passing north of this buoy course 108° 30' true. Plack and white stick buoys mark the reef water on this turn. All buoys are painted oil drums with large white numbers. They are placed on the edge of the reef in deep water, but it is advisable to pass them with 20 yards clearance. Pilot boards vessels at one mile due West of Moro Island. Pilot is optional. Captain Vincente Rezon is stationed at Isabela as Pilot.

## DECLASSIFICATION/RELEASE INSTRUCTIONS ON FILE

U.S. Officials Only

## Approved For Release 2003/10/01 : CIA-RDP80-00809A000500350163-0

## CONFIDENTIAL/US OFFICIALS ONLY

-0-

25X	(1A_

Press. The five piers from west to east are:

Basilan Lumber Company Pier: Wood construction, 600 feet long at the face with 53 feet of water at the west end and 40 feet of water frontal. The pier lies 250 true. If this pier is to be used to load other than Basilan Lumber Company cargo, arrangements must be made with the Basilan Lumber Company prior to the ressel's arrival. Pier has been extended considerably for log loading.

Basilar Lumber Company Tanker Dock: T-Shaped, 210 feet long at the face with 20 feet of water. It has fueling facilities and is equipped with a meter. This dock is used by smaller craft comparable to Interisland tankers.

Santa Clara Lumber Wharf: 250 feet long with 28 feet of water. The wharf is new with fender piles and mooring facilities.

American Rubber Dock: 210 feet long with 26 feet of water.

Western Mindanao Lumber Company Dolphins: 10 dolphins fronting Western Mindanao Lumber Company log pond. Water is 30 feet deep 15 feet away from dolphins and 2h feet deep close to dolphins. Depth decreases eastward.

## 5. Principal Shippers.

756.54 756.543 756.545 756.547

Basilan Lumber Co. Logs and lumber Logs and lumber Santa Clara Lumber Co. American Rubber Co. Rubber, logs and lumber Basilan Plantation Co. Rubber and copra Sumagdan Plantation Co. Logs, lumber and copra Pacific Copra Export Co. Copra Tabac alera Copra Western Mindanao Lumber Co. Logo and lumber Banilan Enterprises, Inc. Logo

index. Stevedering taker is foculty supplied. The rate of loading is about three thousand heard feet of fumber per gang hour and about five thousand neard feet of fureration log Scale per gang hour. The wharves are supplied with life tracks and tumber carriers.

These and Laumeters. The Banilan number Company owns and operator two tug locate. One is a WT small, and the other, a standard Semmile Tug. Fast transfer are also available in case of need. Excellent public launch service between lasheds and Zamboanga is available as follows:

Taabella to Zambounga - 5:00 AM and 6:00 AM daily,
Additional launch at 10:00 noon on
Wednesday, Friday and Bunday.
Additional launch at 2:00 PM on Saturdays

Zambounga to Teabela - 9:30 AM and 12:00 noon daily Additional James at 4:30 PM Saturdays and Sundays.

- . lapuirs. Minor welding and machine repairs can be performed by the Basilan number Company.
- Donnage. Dunnage is obtainable at reasonable rates.
- Medical Facilities. The Basilan Lumber Company has a modern 10 bed hospital equipped with X-ray. Serious cases can be taken to the modern 40 bed Basilan Hospital in Isabela which is equipped with all of the latest medical devices. Three highly qualified doctors and five trained nurses offer 24 hour emergency service.
- H1. Water. Fresh water to no longer available at the Basilan Lumber Company wharf. Emergency needs can be acquired from fresh water sources in Zamboanga.
- The Communications. Post office, telegraph station, and a branch of the Philippine Mational Bank are located in Isabela, Basilan City.

S S	LINGRAPER	SHIELD W	# 27 Sec.	···	
Approve	d For Release	2003/10/01 /US OFFICIA	: CIA-RDP8	30-00809A000	500350163-0